Shipping Box Assembly Guide

All Box Sizes



Step 1: Pop out the flattened box and position it upright in a way that the bottom of the box is facing upwards.



Step 2: First fold the smaller flaps along the crease line and then fold the larger flaps over the top of it.



Step 3: After folding the flaps, seal it with packaging tape. Make sure that the tape starts and ends on the sides, while going across the line where top flaps meet. This becomes the bottom base of the box.



Step 6: You should now have an awesome looking Shipping box!



Step 4: Turn the box upside down so the bottom base is on the floor.



Step 5: Fill the box and seal the top by following the similar steps used to seal the bottom base.